

FLORENCE COPPER INC.

1575 W. Hunt Highway, Florence, Arizona 85132 USA

florencecopper.com

November 1, 2021

Mr. David Albright Manager, Groundwater Protection Section USEPA Region 9 (WTR-4-2) 75 Hawthorne St San Francisco, CA 94105

Subject: Underground Injection Control (UIC) Permit Number R9UIC-AZ3FY11-1

Monthly Update for AL Exceedance at Supplemental Monitoring Well M60-O

Dear Mr. Albright:

Florence Copper is providing this monthly update of supplemental monitoring well M60-O alert level (AL) exceedance under Underground Injection Control (UIC) Permit Number R9UIC-AZ3FY11-1 (Permit).

Florence Copper has been voluntarily monitoring M60-O monthly for radon, and last submitted a monthly update report on October 1, 2021. Table 1 (attached) has been updated to include the most recent laboratory results from the monthly sample collected on September 15, 2021 and received on September 30, 2021. Radon exceeded the AL, but the concentrations are trending downward since July. Results from the monthly sample collected on October 19, 2021 are pending.

Rinsing activities continue at the PTF wellfield. Injection into well I-02 was discontinued in August and September to aid rinsing efforts on the east side of the wellfield. In early October, well I-02 began temporarily operating as a recovery well. Also during October, recovery rates in the wellfield were approximately two times greater than the injection rates. Hydraulic gradients were maintained throughout the month.

Florence Copper will continue monthly sampling of M60-O for radon and will report these results monthly to EPA until the concentration of radon is below the AL.

Please feel free to contact me should you have any questions or comments.

Sincerely,

Florence Copper, Inc.

Brent Berg

General Manager

Cc: Nancy Rumrill, EPA Region 9

Maribeth Greenslade, ADEQ

Table 1. M60-O Monthly Sampling Results

,	(p R) P;				
	(pCi/L)	Radon	arameter		
	2480		UIC AL		
		ł	AQL UIC		
	NA		1/7/21		
	NA		2/22/21		
	AN		3/23/21		
	±308.1	3073.6	4/14/21		
	±915.6	9129	5/18/21		
	±299.4	2985.3	6/15/21		
	347.5	3465.5±	7/19/21		
	307.7	3066.1±	8/24/21		
	299.9	2991.0±	9/15/21		

BOLD values are exceedance of AL and/or AQL NA: not analyzed